



Instructions

Pressure & Temperature Rating

Minimum working pressure 1 bar(100kpa/15PSI)

Maximum working pressure 5 bar(500kpa/70PSI)

Maximum working temperature 50 Celsius Degrees

Caution: Use improper treatment will cause damage to the shower set and cause injury to the user!

Cleaning Materials for Mixers and Showers

Acids are a necessary ingrediants of cleaning materials for removing lime, however please payattention to the following points when cleaning mixers and showers:

- Only use cleaning material which is explicitly provided for this type of application.
- Never use cleaning materials, which contain hydrochloric, formic or acetic acid, as they cause considerable damage.
- Phosphoric acid is also restricted as it can caused damage.
- Never mix any cleaning material with another.
- Never use cleaning materials or appliances with an abrasive effect, such as unsuitable cleaning powders, sponge pads or micro fibre cloths.



Suggest to clean the nozzles every 3 months for daily use, and must clean every 1 month for special Poor Water Places with lime scale or if water flow reduced dramatically.

Important

Residues of liquid soaps, shampoos and shower foams can also cause damage, so rinse with clean water after using.

Please Note: If the surface is already damaged, the effect of cleaning materials will cause further damage.

DO NOT REMOVE the FLOW REGULATOR and CONE MESH WASHER from the rain shower, otherwise, will probably cause damage by improper treatment.